## 1955 SERVICE CRAFTSMAN NEWS INDEX

## JANUARY THROUGH DECEMBER ISSUES

Place this index in front of the 1955 issues of the Service Craftsman News in your binder for ready reference.

ACCELERATOR PEDAL				
		AIR CONDITIONING (Cont'd)		
Hinge Pin Lock Ma	ar. 40	Compressor Part Numbers	June	78
		Compressor Seal Replacement -		
ACCEGGODIEG		1954	July	88
ACCESSORIES Antenna Water Leaks Jar	n 7	Compressor - Service Information - 1955	Teslan	00
Back-up Lamps - 1956 Oc	- ,		July	90
Continental Tire Kit Installation Ap		Compressor Shaft Seal Leaks - 1954 - Repair	Mon	332
Direction Signal Wiring Harness	1. 43	Evaporator Pressure	Mar.	332
- Short Circuits - Correction Ma	ır. 38	Regulators - Type	June	76
Direction Signal Circuit Oc		Freon Capacity	May	56
Direction Signal - Indicator	. 101	Freon Leaks at Compressor	Way	30
Lamp Socket Ap	r. 42	Valve Body	Mar.	53
Electromatic Radio - 1956 Oc		Insect and Foreign Material	141617 •	00
Electric Window Regulator -		Removal	July	90
Service Information Ma	r. 25	Maintenance Procedure - 1955-56	Dec.	166
Electric Windshield Wiper Oc	t. 154	Manual	Feb.	24
Heater - Defroster - 1956 Oc	t. 154	Package Installation	_ 0.00	
Heater Operating Instructions Jan	. 1	Instructions - Correction	July	92
Luggage Compartment and			<b>3 3</b>	
Utility Lamp - 1956 Oc	t. 153			
Power Antenna - 1956 Oct	t. 153	BODY		
Power Seat - 1956 Oct	t. 151	Body Bolt Usage	May	56
Rear Seat Speaker - 1956 Oct	t. 152	Body Changes - 1956	Oct.	98
Rear Seat Speaker - Cone Damage Ma	r. 35	Body Finish - New Type	Nov.	158
Underhood Lamp - 1956 Oct	t. 153	•	Dec.	168
Upholstery Cleaner Apr	r. 43	Body to Frame Interference -		
Vinyl Covers Damage Trim Jan		Elimination	July	92
Windshield Washers Apr		Color Combinations	April	41
Oct		Convertible Top (Water		
Windshield Washer Check Valve Dec	c. 176	Wicking and Staining-1955) -		
		Correction	Dec.	172
		Dash Panel Thump on P56		
AIR CONDITIONING		Cars - Correction	Dec.	173
Compressor - Adding Oil Ma	r. 34	Door Lock Strikers	June	79
1955 Compressor Belt		Headlining Stained (Catalina) -	July	87
Misalignment Ma	r. 33	Correction	Nov.	158

				(0	
BODY (Cont'd.)			CARBURETOR - ROCHESTER FOU	JR-JET (Co Oct.	ont'd.) 106
Insects and Foreign Material -	T. Jee	90	1956 Information	Dec.	165
Removal Paint Discoloration	July June	90 <b>7</b> 5	Overhaul and Adjustments	June	63
Paint Discoloration	July	91	Power Package	June	57
Page Door Look Page	July July	86	Specifications - Adjustment	June	74
Rear Door Lock - Repair Refinishing Precautions	Apr.	44	Specifications - Adjustment	June	17
Service Panels - "Metal Wrap"		77			
Removal	Apr.	43	ELECTRICAL		
Seat Cushion Squeaks -	1101.	10	1956 Battery Information	Oct.	145
Correction	AugSept.	96	Battery Maintenance	July	84
Seat Trim Identification	May	54	Battery to Starting Motor Cable	Mar.	36
Soldered Joint Cracks -	27247	• •	1956 Cigar Lighter	Oct.	149
Correction	Apr.	42	Generator - Air Conditioned		
Vinyl Top - Cleaning	AugSept.	96	Cars	June	75
Winter Care	Dec.	171		Dec.	166
			Generator (Heavy Duty)	Mar.	38
PD AVEG CENTED AT			1956 Generator Regulator	Oct.	145
BRAKES - GENERAL	0-4	101	1956 Instruments	Oct.	149
1956 Information	Oct.	101	Parking and Signal Lamp		
			Corrosion - Correction	July	85
BRAKES - POWER			Safety Aimer - Use of	Oct.	147
Hose Clamps	Mar.	37		Nov.	158
Expander Assembly (Moraine)	Mar.	35	Sealed Beam (New Unit)	Mar.	37
Poppet Valves (Bendix)	June	74		July	91
				Oct.	147
			1956 Spark Plugs	Oct.	145
CARBURETOR - GENERAL			1956 Starting Motor	Oct.	145
Air Cleaner Stud - Replacement			Starter Motor Assembly	Mar.	33
(4-Jet)	AugSept.	96	Tail and Back-Up Lamp		
Carter Carburetor Corrections	Mar.	31	Breakage	Mar.	37
Choke Piston (Rochester 2-Jet)	June	75	1956 Wiring Diagram	Oct.	146
Choke Setting (Carter)	Jan.	8			
Correction to June Service					
News	July	90	ENGINE		
Flooding Diagnosis	Jan.	7	Camshaft Bearings - New Type		0.1
1956 Information	Oct.	105	For Service	July	81
Stalling Due to Icing	Nov.	158	Camshaft Identification - 1956	Nov.	158
			Compression Ratio - 1955 vs 1956	Mari	164
CARBURETOR - ROCHESTER 2-]	EΤ			Nov.	164 105
1956 Information	Oct.	105	Cooling and Lubrication	Oct.	100
			Crankcase Ventilator Outlet	Mar.	37
CARBURETOR - CARTER FOUR-	DADDET		Pipes - Incorrectly Installed Crankshaft Main Bearing Shells	Mar. Mar.	38
Adjustments	Feb.	19	Coil and Ventilator Outlet	Mai.	30
Adjustments on Car	Feb.	13	Pipe Interference	Mar.	40
Air Cleaner Installation	Mar.	40	Cylinder Block and Head Core	war.	40
Circuit Explanation	Feb.	9	Hole and Oil Passage Plug		
Cleaning and Inspection	Feb.	15	Replacement	May	51
1956 Information	Oct.	109	1956 Engine Idle RPM	Oct.	109
1000 Intol mation	Dec.	165	Front Main Bearing Noise	June	74
Overhaul and Adjustments	Feb.	13	Harmonic Balancer Bolt Torque	Nov.	158
Specifications	Feb.	22	Harmonic Balancer Noise -	11011	100
Specifications (SM)	Mar.	33	Correction	Mar.	29
Testing	Feb.	21	Harmonic Balancer Returning	June	77
Unloading (HM)	May	52	Hydraulic Valve Lifter Changes	Jan.	5
ontouring (IIIII)	111th y		1956 Information	Oct.	101
			Main Bearing Cap Lockwashers	Apr.	44
CARBURETOR - ROCHESTER FO	UR-JET		Misfiring Due to Oil in		• •
Adjustments on Car	June	63	Combustion Chamber -		7
Choke Setting (HM)	Nov.	158	Correction	Nov.	161
Cleaning and Inspection	June	65	Oil Filter Element - Replace	Feb.	24
General Description	June	57	Oil Leaks	Apr.	41
•	-			-	

www.PontiacSafari.com					
SUBJECT	ISSUE	PAGE	SUBJECT	ISSUE	PAGE
Sobjec 1	100 011	TAGE	SOBJEC 1	ISSUE	FAGE
ENGINE (Cont'd.)	_		HEATER	_	
Oil Leaks (Rear Main Bearing)	June	77	Operating Instructions	Jan.	1
Oil Pump Gasket	July	91			
Oil Windshield Sticker	May	56			
Push Rod Damage	Jan.	6	HOOD		
Removal Precautions	June	77	Correction of Vibration	Jan.	4
Rocker Arm Damage	Jan.	6	Hold-Open Prop - Use	July	90
Rocker Arm Studs	Mar.	40	Under coating - Cautions	Dec.	166
Rocker Arm Stud Remover					
Available	$\mathrm{Dec}_{ullet}$	167			
Rough Idle and/or High			HYDRA-MATIC - DUAL RANGE		
Vacuum Whistle	Mar.	40	1955 Changes	Mar.	36
Setting Timing	Nov.	158	Control Valve Assembly	_	_
Throttle Linkage -	_		Identification	Jan.	8
Synchro-Mesh	Jan.	6	1956 Information	Dec.	171
Thermo-Gauge - Location	July	91	Oil Cooler Installation	May	54
Timing Chain - Remove	Jan.	3	Oil Cooler Package	Feb.	24
Valve Lifters	Apr.	43	Rear Bearing Oil Seal	37	101
Valve Lifters - Information	June	75	Identification - 1955	Nov.	164
Valve Lifter Plastic Wrap	•	Pr 4	Reverse Drive Flange	<b>A</b>	40
Removal	June	74	Thrust Washer	Apr.	42
Valve Stem Guides -	A	0.0	Reverse Stationary Cone	Jan.	8
Incorrect I.D.	AugSept.	96	Shift Speed Chart	Oct.	116
Valve Stem Oil Shield - Install	Jan.	2 166	Throttle Linkage Adjustment	Jan.	7
Water Distributing Tube	Dec.	100			
			HYDRA-MATIC - STRATO-FLIG	нт	
EXHAUST SYSTEM			Control Valve	Dec.	176
1956 Information	Oct.	117	Flywheel Housing Bushing -	Dec.	1.0
	Dec.	174	Overstaked	Dec.	173
	2000		Front Pump	Dec.	175
FLAT RATE			Front Sprag Failure -	200.	1.0
Flat Rate Information	July	87	Correction	Dec.	174
	Nov.	159	1956 Information	Oct.	116
				Dec.	171
			Neutral Clutch Rebuild	Dec.	174
FRAME			Oil Contamination -		
Frame Changes - 1956	Oct.	98	Replace Oil Cooler	Dec.	173
			Oil Level Check	Dec.	166
FRONT SUSPENSION			Reporting Sprag Failure	Dec.	176
Information - 1956	Oct.	98			
Pivot Pin Installation - 1956	Nov.	157			
			INSPECTION		
FUEL PUMP			Pre-Delivery and 2000 Mile	Nov.	157
High Pressure Correction	Mar.	36			
nigh Tressure Correction	wai •	30			
			NEW MODEL		
FUEL TANK	_		General Information	Oct.	98
Fuel Tank Filter	Oct.	117	1956 Information	Oct.	98
Fuel Tank Specifications	Oct.	118	Paint Information - 1956	Oct.	98
Rear Compartment Floor	_				
Pan Noise	June	78			
			P.I. REPORTS		
GAUGES			Paint Information	Tuno	0.0
Fuel and Oil Pressure			raint intormation	June	80
Readings	Mar.	38			
Oil Pressure Gauge Noise -	TATELT .	50	POWER STEERING		
Correction	July	87	Adjustment on Car	Oct.	121
201 1 0002011	J 442 y	••	Description of Operation	Oct.	119
HANDICAP CONTROLS			General Description	Oct.	118
Accelerator and Brake			Lubrications	Dec.	166

Lubrications

Repairs

May

45

Accelerator and Brake

Hand Control

166

121

Dec.

Oct.

www.PontiacSafari.com SUBJECT	ISSUE	PAGE	SUBJECT	ISSUE	PAGE
RADIATOR			STATION WAGON (Cont'd.)		
Hose Clamps	May	47	Rear End Rebound	May	51
Insects and Foreign Material -			Safari Rear 1/4 Sliding		
Removal	July	90	Window Bumper	June	79
Lower Hose Interference	Jan.	7	Safari Rear Quarter Window		
			Water Leaks	June	78
			Safari Tail Gate and Lift Gate		
RADIATOR GRILLE			Water Leak Correction	May	48
Center Bar Molding Tabs	May	56		Nov.	162
Center Bar Upper Molding	Mar.	40	Tail Gate Cable Stop	Mar.	30
			Tail Gate Lock Outside		
			Handle – Repair	May	50
REAR SUSPENSION			Tail Gate Support Cable	Mar.	30
1956 Information	Oct.	100	Tail Gate Support Cable		
			Retainers - Replace	May	50
			Use of Hoist	Jan.	6
SCHOOL					
G.M. Training Centers	Mar.	39			
			STEERING GEAR		
			Lubricant Capacity	Jan.	3
SERVICE CRAFTSMAN					
Correction to October	Dec.	171			
Correction for November	Dec.	168	STRATO-FLIGHT		
Examination #55-1	Jan.		(See Hydra-Matic)		
Examination #55-2	Mar.				
Examination #55-3	May		CIDI VICOD		
Examination #55-4	July		SUN VISOR	3.6	5.0
Examination #55-5	Oct.		Installation Noise - Correction	May	56 5
			Noise - Correction	Jan.	อ
GHOCK A BOOD BEING					
SHOCK ABSORBERS 1956 Information	Oat	100	SYNCHRO-MESH TRANSMISSION		
1956 Information	Oct.	100	1956 Information	Oct.	109
SHOP MANUAL			TAIL PIPE AND REAR BUMPER		
Corrections to 1955 Preliminary	Apr.	44	INTERFERENCE	Mar.	40
1955 Final Shop Manual -					
Distribution	July	89	TIRES		
			Balancing Tubeless Tires	May	56
			Inflation Recommendation -	witty	00
SPRINGS			'Safari' Station Wagon	July	85
1956 Information	Oct.	100	butuit button wagon	July	00
Rear Spring and Bushing					
Information	Dec.	168	TOOLS		
Shackle to Frame Interference	Mar.	35	Hydra-Matic Reverse Clutch		
			Spring Compressor - J-4670-B	May	53
			Valve Lifter Remover J-3049	May	53
STATION WAGON					
Drip Molding Paint - Repair	Dec.	170	TRAINING CENTERS		
Fuel Tank Replacement	Mar.	37		AugSept.	93
Lift Gate Rattles -			-1 aming contents - opportunity	48pehre	00
Correction	Dec.	170			
Rear End Lower Panel			WEATHERSTRIP		
Interference - Correction	Dec.	166	Mechanical Retaining Clip	Mar.	29