

1956

SERVICE CRAFTSMAN NEWS

INDEX

JANUARY THROUGH DECEMBER ISSUES

Place this index in front of the 1956 issues of the Service
Craftsman News in your binder for ready reference.

SUBJECT	ISSUE	PAGE	SUBJECT	ISSUE	PAGE
ACCESSORIES			AIR CONDITIONING (Cont'd.)		
Electric Window Regulator - Correction of Squeak	Mar.	19	Rancostat Adjustment	Aug.	48
Electric Window Lifts - Rear Quarter Window Upper Stop	Mar.	18	15 lb. Radiator Cap Used in 1957 Air Conditioned Cars	Sept.-Oct.	56
Lubrication of Actuator Jack Screw on Six-Way Power Seat Adjuster	July	35	BODY		
Power Seat "Chucking" - Correction	May	27	Always see that Front Floor Mat is Installed Correctly	Dec.	69
Power Seat Package	Feb.	10	Air and Dust Leak at Door - Correction	June	30
Power Steering Gear - New Adapter Seal	June	29	Bright Metal Corrosion	Mar.	13
Power Steering Gear Leak - Prevention	Mar.	13	Convertible Top Back Window Curtain	July	44
Power Window Service Jumper Harness Assembly Released	Dec.	71	Correction of Convertible Top Noise	Aug.	49
Rear Speaker Control in New Position on Cars With Air Conditioning	July	35	Door Trim Pad Chrome Foil is Replaceable	Nov.	63
Windshield Washer Nozzle - Breakage	Feb.	11	Front Seat Side Panels	Sept.-Oct.	57
Windshield Washer Outlet Hose Incorrectly Connected	Sept.-Oct.	57	Rear Door Window Front Guide Nylon Pan Retaining Clip - Installation	Mar.	20
AIR CONDITIONING			Removal of Water Stains from Convertible Top Inner Lining	Aug.	50
Available Air Conditioning Tools	July	37	Replace Seal when Fuel Tank Filler Neck is Removed	Dec.	67
Correction of Compressor Noise on Air Conditioned Cars	July	38	Seal all Replacement Convertible Tops	Nov.	63
Dip Stick Modification for 1956 Air Conditioned Cars	Sept.	60	Shroud Air Outlet Duct - Air Leak Correction	Mar.	19
Fitting Harmonic Balancer on Cars Equipped with Air Conditioning	Sept.-Oct.	60	Side Roof Rail Weather Strip and Rear Door Weather Strip Interference - Correction	Feb.	11
Generator - New Type	June	32	Squeaks Between Side Roof Rail Mechanical Sealing Strip		
Modify Evaporator Drain Tube to Prevent Flooding	Dec.	71	Striker Sleeve and Door Ventilator Assembly	Aug.	51

SUBJECT	ISSUE	PAGE	SUBJECT	ISSUE	PAGE
BODY (Cont'd.)			CARBURETOR - ROCHESTER 4-JET (Cont'd.)		
Sun Visor Noise Correction	July	42	Rochester 4-GC Secondary Throttle Valve Adjustment	Sept. -Oct.	59
Two Types of Two-Toning Used in 1957	Sept. -Oct.	58	Throttle Body to Bowl Gasket - 285 H.P. Engine	Mar.	15
Use Correct Trim Cement to Prevent "Bleeding"	Sept. -Oct.	58	Vacuum Leak - Correction 285 H.P. Engine	Jan.	3
Use of Leather Sealer on Genuine Leather Trim	July	44		Feb.	5
Weather Strip Lubricant	Mar.	17			
Windshield Area Squeak - Correction	Apr.	23	CLUTCH		
Winter Season Brings Greater Need for Care of Bright Metal	Dec.	67	Clutch Pressure Plate Package	July	44
Zipper Repair Kit now Available for Service	July	38			
			DIFFERENTIAL		
BRACKET, LICENSE PLATE			Companion Flange and Lock Plate - New Type	Mar.	19
Installation Instructions for 1957 Front License Plate Bracket	Sept.	62	Differential Ratio 3.23:1 Made Standard for H.M. Models	Dec.	66
			New Rear Axle Ratio: 285 Horsepower Engines with Hydra-Matic Transmission	Aug.	47
			Pinion Bearings	Jan.	4
BRAKES - GENERAL					
Parking Brake Lever Assembly	Aug.	52	ELECTRICAL		
Rear Brake Drums	June	29	Check Terminal Connections on Back-Up and Tail Lamps	Dec.	72
			Delco Battery Warranty and Adjustment	July	38
CARBURETOR - GENERAL			Generator Bearing Lubrication	June	29
Carburetor General	Sept. -Oct.	53	Horn Relay Corrosion	June	31
Choke Setting (Rochester and Carter 4 barrel)	Mar.	14	Procedure for Lubricating 1957 Speedometer Cable Changed	Dec.	67
Fuel Filter Gaskets May Cause Leak	Aug.	52	Secondary Ignition Resistance Information	Apr.	23
Unloader Adjustment Procedure	Mar.	25	Spark Plugs - New Type	Feb.	11
Unloading Procedure	Jan.	3	Sun Tune-Up Tester Specifications	Apr.	24
1956 Carburetor Trouble Diagnosis	Sept. -Oct.	53	Tail Lamp Wire Retaining Clip Installation	May	25
CARBURETOR - CARTER 4 BARREL			ENGINE		
Air Horn and Choke Housing Redesign	Mar.	14	Allen Uni-Tuner Specifications	Apr.	24
Carter 4-Barrel Carburetor	Sept. -Oct.	54	Camshaft - 285 H.P. Engine	Feb.	5
Correction of Carter 4-Barrel Left Turn "Cut-Out"	July	43	Cylinder Head and Valve Train - 285 H.P. Engine	Feb.	6
Vacuum Piston Spring	June	32	Electrical Specifications - 285 H.P. Engine	Feb.	6
			Fuel Filter	June	29
CARBURETOR - ROCHESTER 4-JET			Harmonic Balancer Torque Changed	May	28
Choke Piston Adjustment	Mar.	14	Heavy Duty Air Cleaner Oil Viscosity	July	38
Diagnosis and Correction of Sticking Secondary Throttle Shaft 1956 Rochester 4GC Carburetors	Aug.	48	Hydraulic Valve Lifter Identification	Feb.	9
Idle Speed and Mixture Adjustments - 285 HP Engine	Feb.	6	New Compression Pressures for 1957 Engines	Dec.	71
1957 Rochester 4GC Float Drop Changed	Dec.	67	Push Rod Guide	Mar.	16
Rochester 4-Jet Carburetor	Sept. -Oct.	55	Rear Main Bearing	Jan.	3
Rochester Dual 4-Jet Carburetors	Sept. -Oct.	56			

SUBJECT	ISSUE	PAGE	SUBJECT	ISSUE	PAGE
ENGINE (Cont'd.)			HYDRA-MATIC - STRATO-FLIGHT (Cont'd.)		
Specifications - 285 H.P. Engine	Feb.	7	Front Pump Locating Screw	June	31
Stall Speed Test - 285 H.P. Engine	Mar.	15	Front Unit Selective Spacer	Mar.	17
285 Horsepower Engine	Feb.	5	Lock-Up When Shifting Strato-Flight From Drive to Reverse	July	35
1957 Engine Idle Speed Adjustment	Sept.-Oct.	56	Low Speed Click in Strato-Flight Hydra-Matic	July	35
FLAT RATE			Neutral Clutch Drive Plates - 1957	Nov.	63
New Flat Rate for Draining and Refilling Fuel Tank	Nov.	63	New Front Unit Drive Torus Spacing Washer Used in Production	Sept.-Oct.	59
Revised Flat Rate Operations	Aug.	52	New Control Valve Assembly Improves 2-3 Shift	Sept.-Oct.	58
Revised Operation	June	32	New Rear Intake Pipe Kit Reduces H.M. Noise in Reverse	Nov.	61
Strato-Flight Time Allowance Revised	Mar.	18	1957 Strato-Flight Hydra-Matic Easier to Shift	Dec.	67
FUEL PUMP			1957 Strato-Flight Manual Valve Body Changed	Dec.	69
Fuel Pump Eccentric Bushing Now Used	Nov.	64	Oil Cooler (Heavy Duty)	Apr.	23
285 H.P. Engine	Feb.	5	Oil Leak at Filler Tube - Correction	Mar.	17
GAUGES			"O" Ring Seals - Front Pump Intake Pipe and Pressure Regulator Plug	Mar.	17
Fuel Gauge Readings - Correction	Feb.	11	Piston Seals - New Type	Jan.	1
HANDICAP CONTROLS			Pressure Regulator Plug Torque	Mar.	17
Accelerator Installation - Left Foot Pedal	Feb.	11	Pressure Tap and Pipe Plug - New Type	June	32
HYDRA-MATIC - DUAL RANGE			Rear Sprag Outer Race Rear Clutch Cylinder and Bushing Assembly - New Type	Apr.	22
Three Sources for H.M. Rear Bearing Oil Seals	Nov.	63	Rear Sun Gear Marking	Mar.	17
Fluid Recommendations	Jan.	2	Reverse Clutch Piston - Identification	Feb.	12
Transmission TV Control - 285 H.P. Engine	May	25	Sealer Recommended for Strato-Flight Front Seals	Aug.	52
HYDRA-MATIC - STRATO-FLIGHT			Shift Valve Body - New Type	Apr.	22
Accumulator Springs - 285 H.P. Engine	May	26	Shims Improve Alignment Between Strato-Flight Flywheel and Flex Plate	Aug.	45
Case Center Support - Passage Enlarged	Jan.	2	Slipping in Reverse	June	31
Changes Made in 1957 Strato-Flight Transmission	Dec.	71	Stall Test	June	31
Control Valve Assembly - New Type	Apr.	21	Strato-Flight Control Valve Assembly Part Numbers Changed	Dec.	68
Control Valve Assembly Changed	July	33	Strato-Flight Output Shaft	Nov.	62
Correcting Leaks at Front of Strato-Flight	Aug.	47	Strato-Flight Reverse Piston Changed	Aug.	51
Diagnosis and Correction of Strato-Flight Torus Drain Back	July	37	Testing and Adjusting TV Pressure on Strato-Flight Hydra-Matics	Aug.	46
Elimination of Fluid Leaks at Strato-Flight Filler Tube	July	38	Transition Valve Ball Check Valve	July	43
Flywheel and Torus Cover Assembly	June	32	Transmission Information	Mar.	16
Front Oil Seal - New Type	Apr.	21	Transmission TV Control - 285 H.P. Engine	May	25

SUBJECT	ISSUE	PAGE	SUBJECT	ISSUE	PAGE
NEWS FLASH			SHOCK ABSORBERS		
Part Number Correction	Mar.	18	1956 Shock Absorber Noise	July	43
PAINT			STATION WAGON		
Lucite Lacquer Information	Feb.	9	Folding Seat Back Rattle -		
Lucite Lacquer Information	June	30	Correction	Mar.	20
Use Care When Cleaning			STEERING GEAR		
Acrylic Lacquer Finish	Sept. -Oct.	53	High-Point Mark on Upper End		
P. I. REPORTS			of Steering Shaft	Sept.	60
Production Engine Number			SUSPENSION - FRONT		
Needed on Engine P. I. Reports	Aug.	51	Crunching and Cracking Noise:		
POWER STEERING			Front Suspension	Aug.	51
Check Water Pump to Cylinder			SUSPENSION - REAR		
Head Inlet Hose for Damage	Aug.	52	Rear Spring and Bushing		
POWER BRAKES			Assembly	Dec.	69
Correctly Install Gasket on			Rear Spring Assembly -		
Bendix Power Brake Hydraulic			New Type	Mar.	13
Reservoir	Nov.	62	Rear Spring Chart - Correction	Apr.	22
New Neoprene Water Pump to			Rear Spring Leaf Liner Package		
Cylinder Head Inlet Elbow			(Butyl Rubber)	Aug.	50
Hose	Sept. -Oct.	59	Rear Spring Rattle - Correction	Mar.	18
1956 Power Steering Gear			TIRES		
Ball Nut Retaining Screw	July	44	Use Care When Changing Tire		
RADIATOR			on New 1957 Wheel Assembly	Dec.	68
Hose Clamps	Jan.	2	TOOLS		
Hose Connections Leak Coolant	May	28	Additional 1957 Tool Informa-		
RADIO			tion Released	Dec.	66
Delco Deluxe Radio Circuit	Sept. -Oct.	56	Black Light Aids in Oil Leak		
1957 Transistor Radio Caution	Dec.	67	Detection	Aug.	50
SERVICE CRAFTSMAN			Modification of Carburetor		
Correction to July Service News	Aug.	50	Holding Stand J-5923	Sept. -Oct.	56
Correction to November Service			Modification of Clutch Unit		
Craftsman News	Dec.	71	Holding Fixture J-6116	Sept. -Oct.	58
Examination #55-1	Jan.		TRAINING		
Examination #56-2	Mar.		Service Training Provides		
Examination #56-3	May		Multiple Benefits	Dec.	72
Examination #56-4	July				
Examination #56-5	Aug.				