

1957

## SERVICE CRAFTSMAN NEWS

## INDEX

## JANUARY THROUGH DECEMBER ISSUES

Place this index in front of the 1957 issues of the Service Craftsman News in your binder for ready reference.

SUBJECT	ISSUE	PAGE	SUBJECT	ISSUE	PAGE
<b>ACCESSORIES</b>			<b>BODY</b>		
Correct Rear Seat Speaker Wiring (1958 Model)	Dec.	94	Body Water or Dust Leak Detection and Sealing Hints	June	52
Electric Clock - Check Direction Hands Move Before Resetting	May	42	Convertible Rear Window - Correct Method of Raising	Feb.	20
Electric Clock Field Installation	Jan.	15	Convertible Top Sealing	June	49
Luggage Carrier Rails - Noise Correction	May	39	Door Glass Run Channel - Tape to Reduce Air Leak	Mar.	30
Power Seat Solenoid Cover - Reducing Rattles	Feb.	18	Hood "Windsplit" Higher	Mar.	32
Reclining Seat Back Service	Apr.	34	Inner Door Panel Seal Proper Reinstallation	Sept.-Oct.	70
Reclining Seat Back Service - Additional Procedures	May	38	Instructions for Safari #2 Seat License Plate Bracket	Dec.	112
Servicing "Safeguard" Speedometer	Nov.	76	Protective Coating on 1958 Bumpers and Radiator Grille	Dec.	98
<b>AIR CONDITIONING</b>			Rear Bumper - Removal of Exhaust Stains	Mar.	30
Air Conditioning Test Specifications - 1957	Sept.-Oct.	71	Rear Door Window Rattles Eliminated by Springs	Feb.	18
Air Filter Housing Assembly Fit	Mar.	31	Safari Model Water and Dust Leak Correction	Mar.	32
Checking	June	45	Seat Rattle Correction - Safari	July	58
Compressor Pulley Bearing Noise	June	47	Use of Shim Proves Valuable in Concealing Headlining Edge	Aug.	61
Filter Coating Material	Mar.	32	<b>BRAKES</b>		
Servicing	July	53	Brake Life - Break-in Period	July	59
Servicing	Aug.	62	Brake Line Interference on 1958 Cars	Dec.	112
Shield Released for A/C Cars	May	41	Parking Brake Cable Clip	Dec.	110
Time A/C Cars at 6 <sup>0</sup>	May	40	Standard Brake Push Rod Clearance - 1958	Nov.	74
<b>AIR SUSPENSION</b>			Vauxhall Brake Pipe Clearance	Dec.	94
Air Ride (Precautions)	Nov.	74	<b>CARBURETOR - CARTER</b>		
Caution Tag in Trunk of Air Suspension Cars	Dec.	94	Carter 4-Barrel Carburetor Service	Jan.	1
Diagnosis Procedure for 1958 Air Ride Manual Valve	Dec.	96			
Removal of Shipping Blocks on 1958 Air Suspension	Nov.	78			

**SERVICE CRAFTSMAN NEWS**

SUBJECT	ISSUE	PAGE	SUBJECT	ISSUE	PAGE
<b>CARBURETOR - CARTER (Cont'd.)</b>			<b>ENGINE (Cont'd.)</b>		
Carter 4-Barrel Carburetor			Crankcase Ventilator Baffle		
Choke Setting (1958)	Nov.	77	Removed	June	48
New Carter Carburetor Released	Dec.	108	Cylinder Wall Glaze Removal	May	41
<b>CARBURETOR - GENERAL</b>			Distributor Shaft, Shimming		
Correction for Carburetor			not Recommended	June	48
Stalling Due to Gum	Dec.	98	Engine Over-run	July	59
Correction of Throttle Lever			Fan and Accessory Drive Belt		
Interference	Dec.	95	Tightening Specifications	Dec.	98
Replacement of Choke Heat Tube	Dec.	111	Gasoline - Foreign Countries	May	37
Throttle Linkage - Coil Wire			Main Bearing Noise Diagnosis	Apr.	36
Interference	Dec.	108	Rocker Arm Cover Gasket		
Throttle Return Check			Sealing	Mar.	28
Adjustment	Dec.	94	Thermostat Replacement	May	43
<b>CARBURETOR - ROCHESTER</b>			Valve Spring Shields - Not		
Float Adjustment Specs. Changed	May	40	Installed on Extra Horse-		
Flooding Condition - Correction	Aug.	61	power Engines	May	41
Rochester Float Specification			Valves - Sticking	June	48
Changed - 1958	Dec.	94	Vauxhall Oil Pan Bolts - Tighten	Dec.	94
Surge Correction - 2 GC	Mar.	30	<b>EXHAUST</b>		
<b>CARBURETOR - TRI-POWER</b>			Muffler & Prop Shaft Clearance		
Throttle Return Spring			on Dual Exhaust Cars	Apr.	33
Installation	May	37	Safari Dual Exhausts Have		
Triple Two Barrel Carburetion			Simulated Outlets	May	41
Service	Mar.	21	<b>FLAT RATE</b>		
<b>COOLING SYSTEM</b>			Flat Rate Clarification	Nov.	77
Engine Coolant Checking	Jan.	15	Flat Rate Operations - 1958	Nov.	80
Radiator Draining - Through			Pontiac Flat Rate Operations -		
Aids in Draining	Jan.	15	1958	Dec.	103
<b>DIFFERENTIAL</b>			Power Steering Time Allowance	Jan.	15
Lubricant Requirement for			Quarter Panel Fender Rear		
Safe-T-Track Differential	Nov.	78	Section - Rewritten	July	54
Clarification on Safe-T-Track			Quarter Panel Replacement Time		
Lubricant	Dec.	95	Allowance Increased	June	47
<b>ELECTRICAL</b>			Times - 1957 Accessory	Jan.	14
Adjustment Provisions Equal for			Tripple Two Barrel Time		
US & Canadian Batteries	June	45	Allowance	Mar.	28
Battery Cable - Re-Route on			Vauxhall Flat Rate Operations	Dec.	99
Cars With Power Steering	July	59	<b>FRONT SUSPENSION</b>		
Battery Specific Gravity	Sept.-Oct.	70	Control Arm Bolts - Tighten at		
Cigar Lighter - Correction			2000 Mile Inspection	May	37
of Shorting	Feb.	17	Front Suspension Wear	Dec.	112
Positioning Directional			<b>FUEL FILTER</b>		
Signal Switch	Dec.	95	Improved Fuel Filter Released	May	38
Stop Lamp Fuse (Change)	Dec.	112	<b>FUEL GAUGE</b>		
<b>ENGINE</b>			Do Not Replace Fuel Gauge		
Anti-Freeze-Wash From			Dash Units Unnecessarily	July	53
Engine Parts	June	52	<b>FUEL INJECTION</b>		
Crankshaft Dowel Pins - Holes in			Adjustment - Fast Idle	July	59
(Corrected in April SCN)	Feb.	18	Corrections to Fuel Injection		
Crankshaft Dowel Pins -			Shop Manual	July	60
Original Pins Again			Nozzles - Released for Sale	July	60
Being Used	Apr.	35	Setting Fuel Injection Enrichment	Nov.	77
			Torque Specification - Nozzle	July	59

**SERVICE CRAFTSMAN NEWS**

SUBJECT	ISSUE	PAGE	SUBJECT	ISSUE	PAGE
<b>FUEL PUMP</b>			<b>INSTRUMENTS &amp; GAUGES</b>		
Fuel Pump and Lines Changed	Jan.	16	Fuel Gauge - 1958 ... "Don't Get Caught" ...	Nov.	77
<b>HEATER</b>			Fuel Gauge - Methods of Checking	Feb.	19
Control Valve Adjusted at 85°	Jan.	16	Replacement of Dash Unit	July	53
Heater Hose Clearance - 1958	Dec.	112			
Heater Operation - Advise Owners of Correct Method	Mar.	29	<b>NEW CAR INSPECTION</b>		
Heater Operation Instructions - 1958 Model	Dec.	94	Inspect New Cars Delivered by Carriers	Mar.	32
<b>HEAVY DUTY TRANSMISSION</b>			<b>NEW MODEL - 1958</b>		
Diagram of Heavy Duty Transmission	Nov.	85	Features Explained ... "Don't Get Caught"	Nov.	77
Service Procedure	Nov.	84			
Specifications (Corrections)	Dec.	111	<b>PAINT</b>		
<b>HYDRA-MATIC - STRATO-FLIGHT</b>			Acrylic Finish Cards - Order From Zone Office	Feb.	20
Accelerator Control Lever Clearance	Dec.	96	Acrylic Lacquer "Bonneville Red" Released	Feb.	18
Aluminum Screen Added in Oil Pan	Mar.	32	Gasoline Spillage	Nov.	77
Bushing - Replacement	July	54	"Jubilee Gold" Released - 1958 Model	Nov.	77
Changes in "Super Hydra-Matic"	Nov.	75	Non-Glare - For Instrument Panel	July	54
Channel Plate Spacer New	May	38	Non-Glare Instrument Panel Paint Discontinued	Dec.	109
Clutch Valve Body Revised	June	46	Service Panels - Proper Cleaning Before Painting	May	40
Control Valve Identification	Dec.	111	Spring Paint Colors Released	Apr.	36
Flywheel Rear Housing Seal Now Black	June	46	Vauxhall Colors and Code Numbers	Dec.	107
Front Pump Starvation - Elimination	Mar.	28	Vauxhall Paint Repair	Dec.	107
Front Unit Driven Torus and Front Sprag Mating	June	47	<b>POLISHES</b>		
Governor Boost Valve Sticking May Cause H.M. to Start in Reverse	May	43	Use of - on Acrylic Lacquer	Feb.	19
Heavy Duty Oil Cooler Available	Jan.	16	<b>POWER BRAKES</b>		
Hot Engine Idle Speed Increased	Nov.	79	Moraine and Bendix Power Brake Unit Identification	Apr.	35
Installation of Hydra-Matic Snap Rings	Dec.	110	<b>POWER STEERING</b>		
Locating Screw Eliminated - Rear Pump	Nov.	76	Ball Nut Retaining Screw - 1956 and 1957	Feb.	20
Mainshaft Pilot Bushings Omitted from 10,000 Transmissions	June	46	Power Steering Gear (Change)	Sept.-Oct.	72
Manual Valve Assembly Procedure	Dec.	95	Power Steering Pump - Air Compressor Assembly - Oil Leakage	Dec.	112
Needle Thrust Bearings - 1958	Dec.	108	<b>PROPELLER SHAFT</b>		
New Governor - 1957	July	59	Center U-Joint Splined Yoke	Nov.	77
1957 Modifications - Review of	June	46	Propeller Shaft, U Joint Serviced Only as Balanced Assemblies	Apr.	33
Red Dye for Testing for Oil Leaks	Nov.	75	<b>RAIL SHIPPED CARS</b>		
Replacement of Intermediate Shaft Snap Ring	Sept.-Oct.	70	Location of Hold-Down Straps on Rail Shipped Cars	Dec.	110
Shift Control Adjustment Procedure - 1957 Transmissions	Mar.	30	Screw Removed on Rail Shipped Cars	Nov.	78
Throttle Rod Ball Joint Stud Retainer - New	May	44			
1957 Torus Cover and Flywheel Used for 1956 Service	Feb.	19			

# SERVICE CRAFTSMAN NEWS

SUBJECT	ISSUE	PAGE	SUBJECT	ISSUE	PAGE
<b>RADIO</b>			<b>TOOLS</b>		
Antenna Trimmer Adjustment	Jan.	13	New Tools Available -		
Removal Procedures	Feb.	19	Carburetor, Air Suspension		
Speaker, Proper Connection of	Feb.	18	Synchro-Mesh	Dec.	97
			Power Brake Seal Installer		
			J-5405 Modification	Jan.	16
			Strato-Flight Rear Pump		
			Removing Tool Released	Mar.	28
			Tool Kit Number (Correction)	Sept.-Oct.	70
<b>SERVICE CRAFTSMAN</b>			<b>TRAINING</b>		
Examination #57-1	Jan.		Automotive Body Repair		
Examination #57-2	Mar.		School Announced	May	44
Examination #57-3	May		Awards	Dec.	111
Examination #57-4	July		Fuel Injection School Announced	June	51
Examination #57-5	Sept.-Oct.		New Car Delivery School Offered	Feb.	20
Service Craftsmen Honored	July	55			
<b>STEERING COLUMN</b>					
Removal From Car With					
Power Steering and Brakes	May	39			
<b>SUSPENSION</b>			<b>VAUXHALL</b>		
Coil Spring Color Chart - 1958	Nov.	79	Brake Line Pipe Clearance	Dec.	94
			Colors & Code Numbers	Dec.	107
			Flat Rate Operations	Dec.	99
			Nomenclature	Dec.	109
			Paint Repair	Dec.	107
			Tighten Oil Pan Bolts	Dec.	94
<b>SYNCHRO-MESH TRANSMISSION</b>					
Counter Gear Thrust					
Washer New	May	43			
<b>SYNCHRO-MESH TRANSMISSION - HEAVY DUTY</b>			<b>WINDSHIELD WIPER</b>		
See Previous Text Under "Heavy			Cable Tighteners Correct		
Duty Transmission"			Wiper "Slap"	May	42